

ANSI/AWS C5.4-93
An American National Standard



Recommended Practices for Stud Welding



American Welding Society



Keywords — arc stud welding, discharge, ferrule,
stud welding, troubleshooting

ANSI/AWS C5.4-93
An American National Standard

Approved by
American National Standards Institute
June 28, 1993

Recommended Practices for Stud Welding

Superseding AWS C5.4-84

Prepared by
AWS Committee on Arc Welding and Cutting

Under the Direction of
AWS Technical Activities Committee

Approved by
AWS Board of Directors

Abstract

These recommended practices for stud welding, prepared by the Subcommittee on Stud Welding of the AWS Committee on Arc Welding and Cutting, are intended to serve as a basic guide for those interested in attaching fasteners by arc and capacitor discharge stud welding.

The variations of the process, stud design, equipment, welding procedures, quality control, and safety precautions are discussed. The information presented will guide the designer and the shop in the utilization of studs in many fields including automotive manufacture, boiler and building construction, farm and industrial equipment, railroads and shipbuilding, aircraft and aerospace, metal furniture, and other metal working industries.



American Welding Society

550 N.W. LeJeune Road, P.O. Box 351040, Miami, Florida 33135

Table of Contents

	Page No.
<i>Personnel</i>	iii
<i>Foreword</i>	iv
<i>List of Tables</i>	vii
<i>List of Figures</i>	viii
1. Process Description	1
1.1 Arc Stud Welding	1
1.2 Capacitor Discharge Stud Welding	3
2. Selection of Method	4
2.1 Fastener Size	5
2.2 Base Metal Thickness	5
2.3 Base Metal Composition	5
2.4 Capacitor Discharge (CD) Method	5
3. Designing for Stud Welding	6
3.1 Base Metal	6
3.2 Stud Design Ratio	7
4. Considerations for Stud Selection	7
4.1 Arc Stud Welding	7
4.2 Capacitor Discharge Studs	11
4.3 Stud Tensile and Torque Strengths	12
5. Equipment for Stud Welding	12
5.1 Arc Stud Welding Equipment	12
5.2 Capacitor Discharge Stud Welding Equipment	17
5.3 Automatic Feed Systems	17
6. Stud Welding Low Carbon and Austenitic Stainless Steels	17
6.1 Base Metal Preparation	17
6.2 Welding Requirements	18
6.3 Welding Technique for Steels	18
7. Stud Welding Aluminum Alloys	20
7.1 Base Metal Preparation	20
7.2 Shielding Gas	20
7.3 Welding Requirements	20
7.4 Welding Technique for Aluminum	20
8. Stud Locating Techniques	23
8.1 Locating with Templates	23
8.2 Locating with Spacers	23
8.3 Fixed Guns	24
8.4 Methods of Ensuring Perpendicularity	24
8.5 Special Accessories	28
9. Quality Control and Inspection	28
9.1 Steel Studs	28
9.2 Aluminum Studs	30

	Page No.
<i>10. Weld Troubleshooting</i>	31
10.1 Cold Welds	31
10.2 Hot Welds	31
10.3 Stud Hang-Up	31
<i>11. Safety Precautions</i>	32
11.1 General	32
11.2 Electrical	32
11.3 Fire Protection	32
11.4 Vision Protection	32
11.5 Hearing Protection	32
11.6 Protective Clothing	32
11.7 Ventilation	33
11.8 Other	33
11.9 Maintenance	33
11.10 References	33
<i>Annex — Commonly Used Metric Conversions</i>	35
<i>Document List</i>	(Inside Back Cover)

List of Tables

Table		Page No.
1	Stud Welding Method Selection Chart	5
2	Typical Combinations of Base and Stud Metals for Stud Welding	6
3	Recommended Minimum Base Metal Thickness of Steel and Aluminum for Arc Stud Welding	8
4	Typical Length Reductions of Studs in Arc Stud Welding	9
5	Weld Flash Clearance for Arc Welded Full Base Studs	12
6	Standard Arc Welding Studs — Tensile/Torque Strengths	14
7	Approximate Tensile and Torque Strengths of Capacitor Discharge Welded Studs	15
8	Typical Stud Welding Conditions for Joining Low Carbon and Stainless Steel Studs to Similar Base Metals	19
9	Comparable Rectangular and Round Studs	21
10	Typical Welding Conditions for Arc Stud Welding of Aluminum Alloys	23
11	Minimum Required Torque Values and Tension Loads for Arc Stud Welding	31

List of Figures

Figure	Page No.
1A Equipment Setup for Arc Stud Welding of Steel	2
1B Power-Control Type Power Source Setup for Arc Stud Welding of Steel	2
2 Steps in Arc Stud Welding	3
3 Steps in Contact Capacitor Discharge Stud Welding	4
4 Steps in Gap Capacitor Discharge Stud Welding	4
5 Steps in Drawn-Arc Capacitor Discharge Stud Welding	4
6 Commonly Used Studs and Fastening Devices for Arc Stud Welding	8
7 Typical Stud Welds with Shrink Fissures in the Upper Portion of the Weld Flash	10
8 Stud Flash May be Accommodated by Use of Oversized Clearance Holes, Use of Gasket Material, and Use of a Dog or Hold-Down Clip	12
9 Commonly Used Studs for Capacitor Discharge Stud Welding	13
10 Oscillograph Traces of Current and Voltages in Arc Stud Welding	15
11 Arc Stud Welding Capacity for DC Power Sources	16
12 Effect of Cable Size and Length on Available Welding Current from a 2000A Power Source	17
13 Portable Arc Stud Welding Equipment	18
14 Recommended Orientation for Welding Rectangular Studs to a Vertical Surface	19
15 Satisfactory and Unsatisfactory Arc Stud Welds	20
16 Arc Stud Weld with Proper Flash Indicative of a Good Weld	21
17 Examples of Satisfactory and Unsatisfactory Capacitor Discharge Stud Welds	22
18 Equipment Setup for Arc Stud Welding of Aluminum	22
19 Simple Template Used to Locate Studs Within $\pm 1/32$ in. (0.8 mm)	24
20 Simple Template for Capacitor Discharge Welds	24
21 Template with Hardened and Ground Bushing and Welding Gun Adaptor	24
22 Locating with Spacer	25
23 Locating from Adjacent Studs	25
24 Locating from Nearby Surface and Previous Stud	25
25 Mounting Gun in a Fixed Position	25
26 Bipod Foot Plate Assembly for 1/2 in. (12.7 mm) Diameter and Smaller Studs	25
27 Bipod Foot for 1/2 in. (12.7 mm) Diameter and Larger Shear Connector Studs	25
28 Bipods for Unusual Surface Contours	26
29 Typical Ferrule Tube Extension Application	27
30 Typical Offset Assembly	27
31 Ferrule Foot Plate	27
32 Typical Extension Assembly	28
33 Stud Hang-Up	28
34 Cold Weld	29
35 Hot Weld	29
36 Bend Test for Welded Studs to Determine Acceptable Welding Procedures	30
37 Method of Applying a Tensile Load to a Welded Stud Using Torque — a Bolt Can Be Used for an Internal Thread	30

Recommended Practices for Stud Welding

1. Process Description

Stud welding is a general term for joining a metal stud or similar part to a workpiece.¹ Welding can be done by a number of welding processes including arc, resistance, friction, and percussion. The arc stud welding process (SW), including capacitor discharge methods, will be covered in this document.

In arc stud welding, the base (end) of the stud is joined to the other work part by heating them with an arc drawn between the two. When the surfaces to be joined are properly heated, they are brought together under pressure. Stud welding guns are used to hold the studs and move them in proper sequence during welding. There are two basic power supplies used to create the arc for welding studs. One type uses dc power sources similar to those used for shielded metal arc welding. The other type uses a capacitor storage bank to supply the arc power.

The arc stud welding processes using these power sources are commonly known as *arc stud welding* and *capacitor discharge stud welding* respectively.

1.1 Arc Stud Welding. The arc stud welding process involves the same basic principles as any other arc welding process. Application of the process consists of two steps:

(1) Welding heat is developed with an arc between the stud and the plate (work).

(2) The two pieces are brought into intimate contact when the proper temperature is reached.

The equipment consists of the stud gun, a control unit (timing device), studs and ferrules, and an available

source of dc welding current. Typical arc stud welding equipment connections are shown in Figures 1A and 1B. The mechanics of the process are illustrated in Figure 2. The stud is loaded into the chuck, the ferrule (also known as an *arc shield*) is placed in position over the end of the stud, and the gun is properly positioned for welding, Figure 2(A). The trigger is then depressed, starting the automatic welding cycle.

A solenoid coil within the body of the gun is energized. This lifts the stud off the work and, at the same time, creates an arc, Figure 2(B). The end of the stud and part of the workpiece are melted by the arc. When the preset arc period is completed, the welding current is automatically shut off and the solenoid de-energized by the control unit. The mainspring of the gun plunges the stud into the molten pool on the work to complete the weld, Figure 2(C). The gun is then lifted from the stud and the ferrule is broken off, Figure 2(D).

The time required to complete a weld varies with the cross-sectional area of the stud. For example, weld time typically would be about 0.13 seconds for a 10 gage (0.134 in. [2.6 mm]) stud, and 0.92 seconds for a 7/8 in. (22 mm) diameter stud. Application rates vary with the size of the stud and other factors such as working conditions. An average rate is approximately six studs per minute, although a rate of fifteen studs per minute is common in many applications.

The equipment involved in stud welding compares with that of manual shielded metal arc welding with regard to portability and ease of operation. The initial cost of such equipment varies with the size of the studs to be welded.

The gun and the control unit are connected to a dc power source. The control unit connections shown in Figure 1 are for power sources designed for secondary interruption, as is the case with motor-generator sets, battery units, and

1. Stud welding is also discussed in the *Welding Handbook*, Vol. 2, 8th Ed., American Welding Society, 1991.